

U. S. D. E. P.

Chi. 148-21 WEST C-15

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.

Cor. I - 1/4 Corner common to Sections 3, and



Corner consists of a Spruce Post (set) in place State condition Very Rotten & Broken

Dimensions above ground Rotted off inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

C 1/4 S. 3

C 1/4 S. 3

C 1/4 S. 3

C 1/4 S. 3

B.T.

B.T.

B.T.

B.T.

Species Jam Spruce Jam Spruce

Diameter 2.29 8" 12" 2.10

Bearing N23°E S26°E S35°W N43°W

Distance 0.15 0.17 0.16 0.14

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Wilbur J. Jager (Signature)

8/12/35 (Date)

Comptroller (Title)

1Aa

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.17

from which this Corner bears

N 26° W


side of Tree

tree 8" inches diameter, on the

NW

Metal Location Poster is on a

5' spruce



(Make sketch of topography near Corner)

T. 148 N. R. 27 W. S. 2 Mer.