

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 28W 6th P. Mer.

~~17~~ Meander Corner common to Sections
16, _____, _____, and 21

Corner consists of a iron pipe (____) in place
State condition good

Dimensions above ground 2 feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>16</u> <u>21</u> <u>MC</u>			

Species Cedar

Diameter 9"

Bearing North

Distance 4 links

Do you believe this to be a genuine Land Office Corner? _____

If not, why? Appears to be original survey corner.

H. E. Altman
H. E. ALTMAN
(Signature)


2/22/20

Acting Forest Ranger

N-10-97

Corner again.
Corner is on edge of Island Lake with a banded line extending S chains east from the corner to the County road.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 136N R. 10E S. 12E Mer.

RANGER'S
FILE COPY

Form 874-9—Revised May, 1918

U. S. Department of Agriculture
FOREST SERVICE

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150W R. 28W 5th P. Mer.

~~1/16~~ Meandor Corner common to Sections
16, _____, and 21


Corner consists of a iron pipe (~~rod~~) in place
State condition good

Dimensions above ground 2 feet inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar

Diameter 9"

Bearing North

Distance 4 links

Do you believe this to be a genuine Land Office Corner? _____

If not, why? Appears to be original survey corner.

H. E. Altman
H. E. ALTMAN
(Signature)


Acting Forest Ranger
(Title)

2/12/40
(Date)

N-10-11

Corner is on edge of Island Lake with a brushed line extending 5 chains east from the corner to the County road. Corner again.

Give any further facts which will aid in finding this from which this Corner bears side of tree inches diameter, on the Metal Location Poster is on a chains distant.



(Make sketch of topography near Corner)