

CORNER T58 R26
RESTORATION
BOOK #7


CORNER RESTORATION BOOK #7

T58/R26W

DIEZGEN

ENGINEERING
FIELD BOOK
No. 5400V

DISTANCES FROM SIDE STAKES FOR CROSS-SECTIONING
 Roadway of any Width
 Side Slopes 1 1/4 to 1



In the figure above Opposite 6 under "Cut or Fill" and under .4 read 9.6 the distance from the side stake to the slope stake at right. Opposite 10 under "Cut or Fill" and under .8 read 16.2, the distance from the side stake to the slope stake at the left.

Cut or Fill	Distance out from Side or Shoulder Stake										Cut or Fill
	0	.1	.2	.3	.4	.5	.6	.7	.8	.9	
0	0.0	0.2	0.3	0.5	0.6	0.8	0.9	1.1	1.2	1.4	0
1	1.5	1.7	1.8	2.0	2.1	2.3	2.4	2.6	2.7	2.9	1
2	3.0	3.2	3.3	3.5	3.6	3.8	3.9	4.1	4.2	4.4	2
3	4.5	4.7	4.8	5.0	5.1	5.3	5.4	5.6	5.7	5.9	3
4	6.0	6.2	6.3	6.5	6.6	6.8	6.9	7.1	7.2	7.4	4
5	7.5	7.7	7.8	8.0	8.1	8.3	8.4	8.6	8.7	8.9	5
6	9.0	9.2	9.3	9.5	9.6	9.8	9.9	10.1	10.2	10.4	6
7	10.5	10.7	10.8	11.0	11.1	11.3	11.4	11.6	11.7	11.9	7
8	12.0	12.2	12.3	12.5	12.6	12.8	12.9	13.1	13.2	13.4	8
9	13.5	13.7	13.8	14.0	14.1	14.3	14.4	14.6	14.7	14.9	9
10	15.0	15.2	15.3	15.5	15.6	15.8	15.9	16.1	16.2	16.4	10
11	16.5	16.7	16.8	17.0	17.1	17.3	17.4	17.6	17.7	17.9	11
12	18.0	18.2	18.3	18.5	18.6	18.8	18.9	19.1	19.2	19.4	12
13	19.5	19.7	19.8	20.0	20.1	20.3	20.4	20.6	20.7	20.9	13
14	21.0	21.2	21.3	21.5	21.6	21.8	21.9	22.1	22.2	22.4	14
15	22.5	22.7	22.8	23.0	23.1	23.3	23.4	23.6	23.7	23.9	15
16	24.0	24.2	24.3	24.5	24.6	24.8	24.9	25.1	25.2	25.4	16
17	25.5	25.7	25.8	26.0	26.1	26.3	26.4	26.6	26.7	26.9	17
18	27.0	27.2	27.3	27.5	27.6	27.8	27.9	28.1	28.2	28.4	18
19	28.5	28.7	28.8	29.0	29.1	29.3	29.4	29.6	29.7	29.9	19
20	30.0	30.2	30.3	30.5	30.6	30.8	30.9	31.1	31.2	31.4	20
21	31.5	31.7	31.8	32.0	32.1	32.3	32.4	32.6	32.7	32.9	21
22	33.0	33.2	33.3	33.5	33.6	33.8	33.9	34.1	34.2	34.4	22
23	34.5	34.7	34.8	35.0	35.1	35.3	35.4	35.6	35.7	35.9	23
24	36.0	36.2	36.3	36.5	36.6	36.8	36.9	37.1	37.2	37.4	24
25	37.5	37.7	37.8	38.0	38.1	38.3	38.4	38.6	38.7	38.9	25
26	39.0	39.2	39.3	39.5	39.6	39.8	39.9	40.1	40.2	40.4	26
27	40.5	40.7	40.8	41.0	41.1	41.3	41.4	41.6	41.7	41.9	27
28	42.0	42.2	42.3	42.5	42.6	42.8	42.9	43.1	43.2	43.4	28
29	43.5	43.7	43.8	44.0	44.1	44.3	44.4	44.6	44.7	44.9	29
30	45.0	45.2	45.3	45.5	45.6	45.8	45.9	46.1	46.2	46.4	30
31	46.5	46.7	46.8	47.0	47.1	47.3	47.4	47.6	47.7	47.9	31
32	48.0	48.2	48.3	48.5	48.6	48.8	48.9	49.1	49.2	49.4	32
33	49.5	49.7	49.8	50.0	50.1	50.3	50.4	50.6	50.7	50.9	33
34	51.0	51.2	51.3	51.5	51.6	51.8	51.9	52.1	52.2	52.4	34
35	52.5	52.7	52.8	53.0	53.1	53.3	53.4	53.6	53.7	53.9	35
36	54.0	54.2	54.3	54.5	54.6	54.8	54.9	55.1	55.2	55.4	36
37	55.5	55.7	55.8	56.0	56.1	56.3	56.4	56.6	56.7	56.9	37
38	57.0	57.2	57.3	57.5	57.6	57.8	57.9	58.1	58.2	58.4	38
39	58.5	58.7	58.8	59.0	59.1	59.3	59.4	59.6	59.7	59.9	39
40	60.0	60.2	60.3	60.5	60.6	60.8	60.9	61.1	61.2	61.4	40

BUONE DITZEL CO.

Property of U.S. FOREST SERVICE

Address Box 308

DEER RIVER MN. 56636

Phone (218) 246-2123

This Field Book contains special paper which is impregnated with resin to make it substantially stronger as well as water resistant. Your field notes will come out sharp and clear even when the page is wet.

Made in U. S. A.

INDEX PAGE

T 58 R 26 4TH PM

6	5	4	4	3	2	1
7	6	5	8			
7	8	13	9	10	11	12
18	INS					13
19	12					24
30						25
31				34		36
				109		
				11		

1 C-11 CENTER QUARTER SEC 4

1967 R.H. McDONALD

SET 2x5' GALVANIZED STEEL PIPE WITH
3" BRASS CAP. MONUMENT STAMPED

T-58NR26W
C 1/4-54

1967

RES No 6807

CEAR 9" N69W 41.9'

BIRCH 8" S39 1/2 W 25.3'

5' STEEL SIGN POST WEST 3.15'

1987 R. MAEN.

FD CORNER IN GOOD CONDITION. PLACED
NEW FSLP TAGS ON BEARING TREES.

20-9

SOUTH 1/16


SEC 4-5

1967 R.H. McDONALD

SET 2' GALVANIZED STEEL PIPE WITH

3" BRASS CAP. MONUMENT STAMPED:

MONUMENT 2.4' ABOVE GROUND



WITNESSED BY

CEDAR 8" S22E 22.8

CEDAR 8" S21W 23.1

5' STEEL SIGN POST NORTH 5.6'

1987 R. MAJIN

FOUND MONUMENT & ACCESSORIES IN

GOOD CONDITION. PLACED NEW FSLP TAGS ON

NEARING TREES

CERTIFICATE FILED

4 BC-9 MC NORTH SHORE NORTH STAR LAKE
BET SEC 4-5

1875 ORIG GOVT SURVEY
SET WOOD POST

SPRUCE 20 N29W 45
W PINE 24 N5E 42

1936 FORM 874-9 O. JUNEAN

Fd decayed post point rotted off
at the ground. Post point was 8" under water.
A small creek crosses an old railroad grade
one chain east of the MC. Location tag
on a 6" birch on the east side of the tree
corner bears N 1/2 S? 45/ks.


W PINE (STP) 24" N5E 45/ks

1938 FORM 874-9 S. PETERSON

CORNER CONSISTS OF AN ASH STAKE IN GOOD
CONDITION 3x3x24. METAL LOCATION POSTER
ON THE SOUTH SIDE OF AN ASH, SOUTH SIDE OF
RAILROAD GRADE DIST 1.25 CHAINS.

W PINE (STP) 24" N5E 0.40 chs 26.40'

CERTIFICATE FILED



6

MC WEST SHORE DEAD HORSE LAKE

BET 5-8

1875 ORIG GOVT SURVEY

SET Wood Post

SPRUCE 8" N 82W 23/ks 15.18'

BIRCH 10" S 73W 15/ks 9.9'

CERTIFICATE FILED

CONT FROM BOOK 1 PG 14

7 E-5 SECTION CORNER 5-6-7-8

1875 ORIG GOVT SURVEY
SET WOOD POST

SPRUCE 8" N64W 10 LKS

CEDAR 6" N27E 15 LKS

SPRUCE 5" S36E 20 LKS


SPRUCE 5" S29W 12 LKS

1940 FORM 874-9 H. HAMALAINEN

CORNER CONSISTS OF 4" CEDAR POST 40"
ABOVE GROUND. POST SET BY CLL CREW FROM
BT.

PINE (STP) S41E 58 LKS

CERTIFICATE FILED



CONT FROM BOOK 1 pg# 48

8 E9 SECTION CORNER 4-5-8-9

1875 ORIG GOVT SURVEY
SET Wood Post


SPRUCE	5	N26W	301ks
BIRCH	10	N81E	501ks
BIRCH	11	S69E	251ks
BIRCH	12	S71W	211ks

1936 FORM 874-9 O. JUNEAU

CORNER CONSISTS OF CEDAR POST. METAL
LOCATION POSTER ON A 8" BASSWOOD ON THE
NW SIDE OF TREE FROM WHICH CORNER BEARS
N40°W .85 CHAINS.

BIRCH	8"	N2E	231ks
BASSWOOD	8	N40W	851ks
BALSAM	6	S46E	451ks
LEDAR	6	S4W	391ks
LEDAR	10	S40W	1/4 CH's 82.5

CERTIFICATE FILED



9

SOUTH EAST 1/16 SECTION 34

RMAIN C KRAUSE


11/14/91 CHAINED 1320' NORTH FROM APPROX EAST

1/16 BETWEEN SEC 3 & 34. PLACED APPROX TAG

ON 6" MAPLE FROM WHICH CORNER LIES S21°W

7 FEET. AGREE WITH PREVIOUS BLUE LINE.

APPROX CORNER ±50 FT NORTH EAST HWY #38




10

SMC SOUTH 1/2 LINE EAST SHORE
KRAMER LAKE SEC 34

11/14/91 R. MAIN C. KRAUSE

CHAINED WEST FROM APPROX SE 1/4 SEC 34
TO KRAMER LAKE. PLACED TAG ON 10" BIRCH
(TWIN) \pm 15 FT FROM LAKE SHORE. OUR LINE
AGREES CLOSELY WITH PREVIOUSLY RUN BLUE
LINE.



CONT FROM BK | TSB R26

11 SECTION CORNER 2-3-3435

MAIN C. KRAUSE

11/15/91 Fd MONUMENT UP 2.3 FT IN GOOD
CONDITION. TAM N84E 11.0 FT NOW DEAD.

BIRCH S20E 29.3 ALSO DEAD. MARK TWO NEW
WITNESSES.

X ROCK 3'x3'x1' S25E 37.60 TO TOP & CENTER

TAMARACK 12" N76E 49.15 TO SPK MKD "535 BT"

(61d) W PENE 18" S85W 8.30 TO SPK

12 MEANDER CORNER BET. SECS. 19-20

ORIG. GOV'T. SURVEY 1873

SET WOOD POST

TAM. 10 S19W 97 LKS. = 64.02'

TAM. 10 S80E 127 LKS. = 83.82'

2534.4'

38.40 CHS. LV. TAM. SWP. SET MC. COR.

12

13 QUARTER CORNER, BET. SEC'S. 8+9

ORIG. GOV'T. SURVEY 1873

SET WOOD POST

BIRCH 10 S40W 60 LKS = 39.60'

BALSAM 4 S78E 22 LKS = 14.52'

CERTIFICATE FILED

13

CERTIFICATE FILED

14 QUARTER CORNER BET. SEC'S, 8+17

ORIG. GOV'T. SURVEY 1873

SET WOOD POST

W. PINE 20 S58E 25 LKs? 16.50'

BIRCH 5 N31W 20 LKs? 13.20'

CERTIFICATE FILED

MEANDER CORNER BET. SEC'S. 8+17
ON WEST SHORE OF GRAVE LAKE
ORIG. GOV'T SURVEY 1873
SET WOOD POST

ELM 10 N80W 10 LKS = 6.60'

BIRCH 10 S30W 39 LKS = 25.74'

CERTIFICATE FILED

END OF
BOOK