Index No. E 25

CASS COUNTY LAND CORNER RECORD

T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____

NE 12 Corner common to sections 1, 12, AND 6, 7-135-31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees				
Species	TAM.	TAM.	TAM	ASPEN
Diameter	8"	7"	14"	8"
Bearing	N68E	S58E	N80 3/4 W	S49 1/4 W
Distance	134 LKS.	77 LKS.	142 LKS.	151 LKS.

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

1922 - TWP (Byron) road order - iron rod set

1941 - State Hwy Dept - assumed corner at intersection Rds N-S-E-W 52.8' W. of new ℄

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1988 By CASS CO & COMSTOCK & DAVIS

Location filed _____

Monument NO RECOVERY

2000 JULY - CCSO

Fnd. inplace; 2" ODIP, dwn. 0.3', Top of pipe is broken. Located 12'W of TH 64 & ¼ 76th St. S.W.

REF TIES:

(TAG) Light Pole N 73°E 110.37'

P.K. in S. End 18" CMP S63°E 56.20'

(Fnd.) P. Pole S 71°W 71.15'

(not) P.K. in N. 24" CMP N 54°W 25.93'

* dist. to dbl. hd. nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____