

Norway
Lake
M.C. No 6 In place
M.C. No 19 Lost.
M.C. No 18 In.
M.C. No 20 In place
139 Lks Govt Ch = 137 My Chain
23.05 Govt Chain = 22.70 My Chain
16.95 Govt Ch = 17.05 My Chain
N.E. Cor of Sec 31. T138 N R29 W. In.
M.C. No 21 In place
This is where I Established 1/4 post, by cuting hole in the ice, then run my line 1 mile South to opposite 1/4 corner. Is this proper?
85.09 Chains
N
SCALE
400 feet = 1. inch
28.75 Govt Ch = 29.78 My Chain
Line
1/4 post In place
Streight
S-T-R-E-I-G-H-T
43.34 My Chain
River
L-I-N-E
This is where I put in the centre of the section. Is it right?
40.09 My Chain
L-I-N-E
40.00 Govt Ch = 40.10 My Chain
1/4 sec In.
PLAT of Sec 31. Twp 138 N. of Rang 29 W. 5th P.M.
"Where is the centre"
Surveyed by
John W. Curo.
Pine River
Minn
April 1907.
Norway
S-t-r-e-i-g-h-t
40.00 Govt Ch = 40.10 My Chain
N 5° 20' E.
S.W. Corner of Township 138. Rang 29. 5th P.M.
40.80 Govt Ch = 41.06 My Chain
Var 8°
1/4 Sec post. In place.
40.00 Govt Ch = 40.53 My Chain
93° 10'
S.E. Cor Sec 31. T138. R29. In place.
#4396
14