CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

__CENTER QUARTER__ Corner of Section __30__ ,Township __144__ ,Range __30__ , __5th__ P.M.

STATE OF MINNESOTA, County of __CASS.__

At the corner location shown on the sketch:

☒ On __3/2/81__ found a __GLO brass cap monument in place as set in 1930.__
　　　DATE

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ placed a _____
　　　DATE

SKETCH OF REFERENCE TIES

-N-

Nail in
Ash
S 58 W 28.40'
Scribed

O

Nail in
6" Y. Birch.
S 47 E 44.70'
Scribed

Nail in
7" Ash
S 16 W 26.22'
Scribed

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Gary H. Stevenson　　　_9-11-82_
　　SIGNATURE　　　　　　　　　DATE

Registration No. __12684__

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER　264955

County of __Cass__

I hereby certify that this document was filed in the Co. Recorders office at _10:16 A_ .M. on the _14_ day of _Sept._ A.D., 19 _82_

County Recorder _Beulah Hendricks_

By _MS_ ,Deputy

DOCUMENT NO. __264955__

Mn/DOT 2105 (4-77)

Statement of Evidence:

1930   U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 14" Tamarack N 78½ E 70 links and 10" Tamarack S 23½ W 88 links.

1934   U.S. Forest Service records show the following: CCC records show brass cap monument and two Tamarack bearing trees found.

1981   U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in good condition up 5". The following bearing trees were found: Tamarack stub N 79 E 46.2' and Tamarack stub S 24 W 58.1' with scribe visible. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 2.7' west and 2.9' north of the corner.

1982   On Sept. 7 I visited the corner and found items as per the 1981 USFS reports. I accepted the monument as marking the same position as when set in 1930 by the GLO resurvey based on bearing tree evidence.