# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section _31_ , Township _134_ , Range _31_

_5TH_ Principal Meridian, State of Minnesota, County of _____Cass_____

At the corner location shown on the sketch:

☐ On _____ found a _____
                 DATE

_____

☐ left monument as found   ☐ lowered monument   ☐ removed monument (explain)

☒ On _11/16/05_ placed a _1/2" Iron pipe with cap #17253_
       DATE

_____

SKETCH OF REFERENCE TIES

SPIKE IN N.E. FACE
OF 12" BIRCH

SPIKE IN E. FACE
OF 19" R. OAK

N05°W 42.4

N40°W 55.2

NEW FENCE LINE

OLD FENCE

11'±

OLD FENCE LINE

S89°50'30"W 5250.19

WEST 19.2

N88°44'53"E 2602.05

NORTHWEST CORNER
SEC. 31, T. 134, R. 31
FOUND 1/2" PIPE CAPPED R.L.S. 17253 IN PLACE

SPIKE IN N. FACE
OF 6" R. OAK

NORTHEAST CORNER
SEC. 31, T. 134, R. 31
FOUND 1.5 INCH PIPE IN PLACE

OLD FENCE

S01°10'34"W 5315.51

SOUTH QUARTER CORNER
SEC. 31, T. 134, R. 31
FOUND 1/2" PIPE CAPPED R.L.S. 17253 IN PLACE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

signature   _1/6/06_
SIGNATURE   DATE

Registration No. _17253_

☒ Land Surveyor   ☐ Professional Engineer

☐ County Surveyor ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. Recorders office at ___ .M. on the _____ day of _____ A.D., 20___

County Recorder _____

By _____ , Deputy

DOCUMENT NO. _____

PAGE _1_ OF _2_ PAGES

Statement of Evidence

North Quarter Corner, Section 31, T. 134N. R. 31W., 5th P.M.

1869 — Wood post was set for corner.

November 2005 — Westwood Professional Services sets 1/2" pipe capped R.L.S. 17253 at the intersection of the old fence lines, recognized by property owners as the Section Corner, the ties to which are on the front of this certificate.