Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X _____ Y _____

N1/4 4 Corner common to sections 4 AND 33-138-31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	TAm.	TAm		
Diameter	4"	9"		
Bearing	N46E	S23W		
Distance	7 LKS.	16 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "A" P330-340

Monument FND OLD GOVT B.T: 9" TAm S23W 10.6 (Down)

SET 4x4x48" TAm POST

also on microfilm - roll 115 BK85 P.179

Evidence of Subsequent Corner Restoration

Year of search 1957 By CCHD

Road plan shows corner assumed at ℄ and fence to North.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

(A-11)

Subsequent Corner Restoration

Year surveyed 9/2002 By CCSO

Location filed #2002.011

Monument Co. Rd #2 construction, dig 6'x8'x6' hole, no corner evidence found.

8/2005 - CCSO - Set PK nail, 0.5' South of new ℄ Co. Rd #2, at 1908 prorata distance and old ℄ location.

12" Ash	N8°W	71.14'*
10" Ash	S42°E	66.44'*
9" Ash	S54°W	93.10'*

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____