Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 3 Corner common to sections 2, 3 AND 34, 35-140-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees					Original Bearing Trees Found			
Species	TAM	TAM	TAM	TAM	Species			
Diameter	12"	10"	10"	10"	Diameter			
Bearing	N20E	S88E	S20W	N10W	Bearing			
Distance	18 LKS	44 LKS	6 LKS	13 LKS	Distance			

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-9", & "E-8"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P.317 FND GOOD B.T.: TAM 10" N10W 13 LKS, SET 3X30" I.P. IN OLD POST HOLE

Bearing Trees, Reference Objects			
Species	TAM	TAM	W. BIRCH
Diameter	6"	7"	5"
Bearing	S69E	S69W	N35-15W
Distance	40.2'	51.6'	63'

Evidence of Subsequent Corner Restoration

Year of search 1939 By CCC

Washburn Lake - BK# 12 P. 13

Start No. from Center of road

1938- BK# 13 P. 4- Fnd 2 B.T.S.: 6" Tam S16E 32.1' 6" Tam S34W 51.9', Pile of rocks w/7" post N34E 30.2' this corner is 5300' from South

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 4/01 By CCSO

Location filed file #2001.017

Monument Found 2" ONIP, down 0.3', 2'± S. of & CR #47. Witnessed as follows:

P. Pole N54°W, 81.27'*
6" Ash N33°E, 122.71'*
10" Tamarack South, 47.21'*
8" Ash S37°W, 47.85'*
*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____