Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

N1/4 5 Corner common to sections 5 AND 32 - 140 - 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument POST

Bearing Trees

Species	TAm.	SPRUCE
Diameter	20"	8"
Bearing	N26½W	S54½W
Distance	45 LKS	10 LKS.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK

Location filed COUNTY BOOK C" P328

Monument FND POST AND OLD B.TS: TAM STUMP 20" N11/2W 29.6', 8" SPRUCE S45E 6.5' SET 2"x48" IRON PIPE 1922 COUNTY RESURVEY "E-9" BEN CLARK

Evidence of Subsequent Corner Restoration

Year of search 1980 By CO. HWY DEPT

FND 1½" I.P. CCRD#47

1942 - JOHN CUEO, BOOK "D" P325 FND CORNER.

1939 - CCC - WASHBURN LAKE - BK#12 P.37 at 2660' from east... Fnd I.P. 1" and Pine post Scribed

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

A-7

Subsequent Corner Restoration

Year surveyed 1998 By Landecker & Assoc.

Location filed CCSO

Monument Found 2" IP, Survey info indicates monument in place

2/2000 - CCSO found 2" ODIP, near PI of road grade, and witnessed:

2"Ash N 42°E, 19.54' *
6"Ash S 57°W, 17.91' *
12"Ash N 55°W, 12.88' *

*distance to double head nail

April 2000 R. Mustoren #832 (cert. of Sur. Shows mon. found)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____