Index No. G 13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____

E 1/4 9 Corner common to sections 9,10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1864

Original monument LOST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	OAK	OAK
Diameter	9"	5"
Bearing	S50E	N35W
Distance	13 LKS	8 LKS

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1922 By BEN CLARK

Location filed COUNTY RESURVEY "E-9"

Monument IRON MONUMENT

1919, BEN CLARK, COUNTY BOOK "C" P320 SET 2 1/2 x 48" I.P.

Evidence of Subsequent Corner Restoration

Year of search 1982 By CO. SURVEYOR

FND 2 1/2" PINCHED I.P. DOWN 0.4' IN ℄ N-S ROAD

OLD FENCE EAST - SOUTH 6.5'

DEC. 1918, Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	POPLAR	POPLAR
Diameter	6"	5"
Bearing	S56E	N74W
Distance	24.5'	25.4'

Bearing Trees, Reference Objects

ASPEN STUMP	BIRCH	R. OAK
15"	10"	8"
N84E	EAST	N45W
17.7'	50.5'	71.28'
	NAIL N. SIDE	NAIL NE SIDE

Subsequent Corner Restoration

Year surveyed 1999 By CCSO

Location filed CCSO

Monument 2" Pinched top I.P., down 1.3' in ℄ Co. Rd #56, witnessed as follows:

10" Birch, S 75° E, 50.54' to 20d spk fd.

10" R. Oak, N 42° W, 71.28 to 20d spk. fd.

7" W. Pine, S 25° W, 81.13 *

* denotes double head spk.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____