Index No. J 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 29 M. 5TH Coordinates: X _____ Y _____

NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	BL. PINE	BL. PINE	BL. PINE	BL. PINE
Diameter	5"	6"	5"	6"
Bearing	N75½E	N33W	S42W	S26E
Distance	35 LKS	64 LKS	17 LKS	33 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "A" P378-381

Monument FND HUB PREVIOUSLY SET BY MOULTON FROM OLD COVT B.T.S SET 2x48" CAPPED GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1939 By JOHN CURO

BOOK "D" P. 220 - FND 2½ x 48 I.P. IN CONCRETE - TOP BENT - RESET BELOW RD SURFACE (24")

10" POPLAR S19-25E 83.0', 8" C.F.P. S88-57W 31.60'

Bearing Trees, Reference Objects

Species microfilm - roll 145 BK 226 P 129

Diameter this work done in 1935 - checked

Bearing in 1939

Distance

Bearing Trees, Reference Objects

BIRCH	W. PINE	J. PINE	TELE. POLE	TELE POLE	J. PINE
4"	24" STUMP	8"	10"	6"	7"
N21-25E	N26-33E	N63-30E	NBW	S52-25W	S40-40E
43.93'	75.10'	61.30'	163.60'	27.05'	73.04'

J-9

Subsequent Corner Restoration

Year surveyed 1947 By WALTER HAROLD CURO

Location filed microfilm - roll 156 BK 271 P. 104

Monument End tres & Capped pipe set 6" under road surface

Nov. 1910, Tuperd order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____