Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Bearing Trees

Species	Bl. Pine	Bl. Pine	Bl. Pine	
Diameter	8"	4"	10"	
Bearing	N67E	N25½W	S78E	
Distance	43 Lks	29 Lks	31 Lks.	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1908 By John Curo

Location filed County Survey Record Book "A" P. 154-155

Monument Found Old Govt B.T.S: 8" Bl. Pine N67E 28.4' 4" Bl. Pine N25½W 19.1' 10" Bl. Pine S78E 20.5'; Set 8x8x36" Cement Post

1950, Harold Curo, Book "D" P352 Found N.W. B.T. Stump Set I.M.

Bearing Trees, Reference Objects

Species	R. Oak	R. Oak	Elm	Elm
Diameter	12"	10"	11"	10"
Bearing	N62E	S25-54E	S47-46W	N55-42W
Distance	44.70'	23.43'	30.85'	93.90'

1950 TIES

Evidence of Subsequent Corner Restoration

Year of search 1951 By Harold Curo

County Book "D" P.387 Found Corner

Bearing Trees, Reference Objects

V - 9

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - ELDO SHORE

HAROLD CURO 1950

Certificate - Jim Nielsen - MnDOT - 1983

Doc. # 2679600

Found 1½" iron pipe 5" below road surface.

Ties: 8" Jack Pine North 35.59'; 14" Elm N55° 27' W 94.0' (1948 BT); 10" Jack Pine N45W 68.75'; 24" Norway Pine N5E 50.28'; 10" Jack Pine N35E 39.42'.

JAN 2002 D. VANDECKER

CERT of SUV SHOWS MON FOUND

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____