Index No. J21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 26 M. 5TH Coordinates: X _____ Y _____

NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees				
Species	SPRUCE	SPRUCE	SPRUCE	TAM.
Diameter	5"	4"	4"	4"
Bearing	S3W	S65E	N15W	N27E
Distance	47 LKS.	39 LKS	8 LKS	27 LKS

Original Bearing Trees Found				
Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed ? By GEO. A. RALPH

Location filed COUNTY SURVEY RECORD BOOK "B" P. 86-87

Monument SURVEY OF STATE RURAL HWY #83 &

TIES - SEE BOOK 'B' P. 86-87

1920 JAMES FLYNN, COUNTY SURVEY 'E - 1½" I.M.

1920, J. FLYNN, BOOK "C" P383. FND STAKE - SET 2½" x 30" I.M.

Bearing Trees, Reference Objects				
Species	C.F.P.	Spruce	Spruce	
Diameter	CEDAR			
Bearing	N88W	NW	NE	
Distance	19.4'	69.5	53.0	
	1920 TIES	S.R.H. TIES		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

→ also on microfilm - roll 115 BK82 P. 26, 50

Bearing Trees, Reference Objects			

J-21

Subsequent Corner Restoration

Year surveyed 10/1995 By R. Main, C. Krause USFS

Location filed USFS Cass Lake

Monument 2" iron pipe, drove 4" below road surface. Witnessed as follows:

7" Tamarack N66°W 100.00'

4" Tamarack S68°W 79.57'

7" Tamarack S11°E 128.67

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____