Index No. R 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____

N1/4 25 Corner common to sections 24,25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument Post

Bearing Trees

Species	POPLAR	BL. OAK		
Diameter	8"			
Bearing	N10W	S15W		
Distance	20 LKS	11 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By LINCOLN MACKEY

Location filed COUNTY BOOK "E" P. 379

Monument SET 2½ x 30" IRON PROPORTIONALLY.

Bearing Trees, Reference Objects

Species	W. ASH	MAPLE		
Diameter	8"	6"		
Bearing	S2E	N26E		
Distance	26.7'	53.4'		

Evidence of Subsequent Corner Restoration

Year of search 11/1940 By R.T Defant

874 CCC Notes Found iron pipe, good condition, 6" high.

Bearing Trees, Reference Objects

Ash (FSLP)
9"
NE
7.92'

R-23

Subsequent Corner Restoration

Year surveyed 11/67 By J. Ekstrom USFS

Location filed USFS Cass Lake

Monument 2" galv. pipe.

9/69 - W. Okerman, USFS found iron pipe, FLSP on 1940 Ash and adds:

FSLP Elm 13" S 25°E 21.2'

9/03 - R. Main, USFS found iron under 10" Elm windfall. 1969 Elm gone, add FSLP to following:

6" Ash N80°W 4.5 to spk

DGPS = 47°00'23.15883, 94°02'22.83905

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____