Index No. J-K 6

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections 17

ON RE-ESTABLISHED ORIG. MEANDER LINE 16.22 CH. S. OF W. 1/16 BTWN 8 & 17



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1 X 36" I.P. W/BRASS CAP

S17 W 1/4 S17 W SMC 1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	MAPLE	MAPLE		
Diameter	7"	14"		
Bearing	N3-30E	N55-30W		
Distance	39 LKS	42 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN 1964

Found GLO monument in good condition; 14" Maple N55°30' W 42 LKS now 16". New ties: 6" Maple N48W 10.2'; 8" Maple S17W 32.75'.

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____