Index No. J-K 7

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections 17

ON RE-ESTABLISHED ORIG. MEANDER LINE - 12.70 CH. SOUTH OF 1/4 BTW 8-17



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/BRASS CAP

S17 C | S17 C SMC 1918

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	BASSWOOD	MAPLE		
Diameter	9"	10"		
Bearing	S30-30E	S28-45W		
Distance	77 LKS	52 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL O'Rourkow - 1964

Found GLO monument in good condition.

9" Basswood S30°30'E 77 LKS; 10" Maple S28°45'W 52 LKS now 12". New ties:

5" Maple S33W 16.8'; 7" Oak S56E 13.85'

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____