Index No. 0 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

SE 1/16 Corner common to sections 1



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1X36" I.P. w/BRASS CAP

SE 1/16 S1 1917

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	J. PINE	OAK		
Diameter	10"	8"		
Bearing	S54¼E	S24¼W		
Distance	40 LKS	177 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo

Location filed _____

Monument Found GLO monument broken. Set 2" x 60" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	W. Oak	R. Oak	Maple	
Diameter	7"	8"	5"	
Bearing	S15W	S5E	S30E	
Distance	102.57'	98.88'	71.50'	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - WALT CURO - 1981

DOC. # 2602622

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____