Index No. E 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

E1/16 Corner common to sections 1, 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 E1/16 51 512 1917

Original monument 1X36" I.P. w/Brass Cap

Original Evidence Found

Year of search 8/01 By CCSO

Monument found GLO Brass Cap

Bearing Trees

Species	R. OAK	W. OAK		
Diameter	6"	10"		
Bearing	N 52 3/4 W	S 67 W		
Distance	135 LKS	240 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 8/01 By CCSO

Location filed file #2001.037

Monument GLO Brass Cap, down 2.0', on ℄ Hwy #200, 30'± W. of pond, 55'± E. of Drive.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	R. Oak	Ash	Tw. R. Oak	
Diameter	12"	10"	10"	
Bearing	N 58° E	S 11° E	S 11° W	
Distance	91.70'	48.03'*	74.04'*	

*distance to double head nail

Bearing Trees, Reference Objects

E-24

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____