Index No. F22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

N.W. 1/16 Corner common to sections 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1X36" L.P. w/BRASS CAP

NW 1/16 S12 1917

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	R. OAK	R. OAK		
Diameter	12"	14"		
Bearing	S10 1/2 E	S31W		
Distance	120 LKS	218 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1964 By William Okerman

Location filed _____

Monument Found GLO monument in good condition; 12" R. Oak S10½E 79.20' now 23"; 14" R. Oak S31W 143.88' now 20".

Bearing Trees, Reference Objects

Species	Maple	Elm	Oak	
Diameter	6"	9"	23"	
Bearing	N40E	S86E	S10 1/2 E	
Distance	30.35'	42.40'	79.20'	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1964

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____