Index No. H 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

C.S. 1916 Corner common to sections 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917

Original monument 1X36" I.P. W/BRASS CAP

5 1/16 C 1 5 1/2 C 1917

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	POPLAR	WHITE OAK		
Diameter	5"	10"		
Bearing	S 25 3/4 E	S 73 W		
Distance	26 LKS	110 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Monument Found GLO monument in good condition; 10" W. Oak S 73 W 72.60 now 15".

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	OAK	OAK		
Diameter	5"	12"		
Bearing	S 18 1/2 W	N 30 W		
Distance	23.90'	26.30'		

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____