Index No. V 9-10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

MC # 37 Corner common to sections 28, 33



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	N. PINE	POPLAR		
Diameter	6"	5"		
Bearing	N33W	S60W		
Distance	36LKS	48LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 9/61 By USFS R.H.M.

Location filed USFS Book pg 67

Monument Search for corner & BT's 3 hrs. Bank eroded.

Evidence of Subsequent Corner Restoration

Year of search 9/73 By USFS C. Krause

Burned & rotted stumps, nothing positive.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

V, 9-10

Subsequent Corner Restoration

Year surveyed 6/05 By CCSO

Location filed #2005.019

Monument Set Alum. County Monument at prorata position. 25'± to Lake

14" R. Oak N68°W, 31.27'*

12" B. Oak S 4° E, 32.41'*

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____