Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 25 M. 5TH Coordinates: X _____ Y _____

NE 5 Corner common to sections 4,5 AND 32, 33-143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871

Original monument POST

Bearing Trees

Species	SPRUCE	FIR	SPRUCE	ASPEN
Diameter	14"	4"	10"	12"
Bearing	N80E	S69E	S4W	N20W
Distance	14 LKS	15 LKS	10 LKS	22 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1922 By J.H. FLYNN

Location filed COUNTY BOOK D P.52

Monument FND SPUCE & ASPEN STUMPS SET 1/2" X 44" I.P. 1924, J.H. FLYNN, BOOK D P.132 FND IRON AND TIES

1933 CCC, A. Jager found iron pipe.

Bearing Trees, Reference Objects

Species	BIRCH	ASPEN		
Diameter	12"	7"		
Bearing	S84E	N81W		
Distance	27'	40'		
	1922 TIES			

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM

FND 3/4" X 20" I.P. - SET 2½" X 28" ALUM POST W/ ALUM CAP.

T143N R25W

532 | 533

5 5 | 54

T142N

1976

Bearing Trees, Reference Objects

BALSAM FIR	W. BIRCH	BIRCH	ASPEN
8"	6"	5"	20"
N56E	S38E	S34W	N71W
71 LKS	66 LKS	79 LKS	108½ LKS

A-9

Subsequent Corner Restoration

Year surveyed 1978 By G. Stevenson

Location filed Landecker & Assoc, Walker office

Monument Found Alum. pipe.

1983 USFS G. Kosenko found 2½" Alum. mon. with 3½" Alum. cap.

9/2001 Landecker & Assoc. found Alum. Cap monument, down 18", on & of road, BLM 1976 witness trees NW & SE, and add the following

8" Maple	N48°W,	84.70'
12" Balm of G.	N50°E,	46.86'
7" Oak	S18°E,	87.20'
10" Oak	S23°W,	99.42'
Sign Post	West,	16.5'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____