Index No. U-9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
S 1/16 Corner common to sections 29 ; 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1" x 36" I.P. w/ Br. Cap

Bearing Trees

Species	W. Oak	R. Oak		
Diameter	8	5		
Bearing	S 38 W	N 10½ E		
Distance	106 lks	384 lks		

Original Evidence Found

Year of search 1992 By USFS
Monument found GLO Brass Cap

Original Bearing Trees Found

Species	R. Oak	R. Oak	R. Oak	Sign Post
Diameter	10"	12"	7"	
Bearing	N 42° E	S 83° E	S 51° E	North
Distance	98.20	61.78	66.20	2.2'
	6od spk	6od spk	6od spk	

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO
Location filed CCSO
Monument Found GLO Brass cap monument 47'± E. of Co. Rd #153. 1992 witness trees in good condition

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

U-9

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed
Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____