Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	Spruce	Tam	Spruce	Spruce
Diameter	7"	6"	7"	6"
Bearing	N72W	N4½E	S57E	S29W
Distance	8 LKS	4 LKS	16 LKS	11 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed ? By GEO. RALPH

Location filed COUNTY SURVEY RECORD BOOK B" P97

Monument FND OLD POST - OLD B.TS: 8" TAM N50E 4', SPRUCE S65E 11', SPRUCE N52W 4'

also on microfilm- roll 115 BK82 P. 36

Bearing Trees, Reference Objects

Species	TAM	TAM	SPRUCE Stone	CEDAR
Diameter	12"	8"	10"	6"
Bearing	S34-30E	N28-30E	N64W	S29W
Distance	47.5'	42'	82.9'	57.2'

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co. Hwy Dept

State Rd #4 Book 154 Page 16

APPROX. Corner.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By L. Leuelling RLS 16089

A brass capped steel mon. was set at E of Co. Rd. 35. Position of corner perpetuates recovered GLO corner at between 1910 - 1915.

REF. TIES:

12" W. Oak	N 3° W	179.90'
20" W. Oak	N 66° E	128.43'
P. Pole	S 73° E	182.44'
P. Pole	S 77° W	226.87'
Std. Sign Post	SOUTH	33.00' (FS 54-9)

CERT. OF LOCATION 5/17/99

DOC. # 412843

2004? L. Leuelling # 16089

Cert. of Sur. shows steel mon. w/brass cap

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____