Index No. P9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____

E1/4 20 Corner common to sections 20/21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Cedar	Cedar		
Diameter	6"	7"		
Bearing	S42E	N60W		
Distance	14Lks	12Lks		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSM RLS# 16089

Set corner from orig. GLO bearing trees set a .75"X 8.8' alum. rod w/ 3" Alum. Stamped cap, up 10" above ground.

Bearing Trees, Reference Objects

Ash	Ash	Ash		
6"	7"	7"		
N46°W	N60°E	S12°E		
46.99'	20.07'	68.54'		

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

(Cont) –

Remains of 7" Cedar N60°W 12lks (7.92')

" " 6" Cedar S42°E 14lks. (9.24')

Orig. GLO Bearing Trees

CERT. OF LOCATION 5/17/99

DOC. # 412849

2004? L. Levelling #16089

Cert. of Sur. shows alum. mon. with alum. cap

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____