Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 35 Corner common to sections 25, 26, 35, 36



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Tam	Tam	Tam	Tam
Diameter	8"	8"	6"	6"
Bearing	N80W	S10W	S47E	N48E
Distance	13 LKS	31 LKS	31 LKS	25 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1920 By GLO

Location filed Sec. of State

Monument Found all 4 orig B.T. STUMPS
Set 2x36" LP. w/brass cap T143N R26W

S26	S25
S35	S36

1920

Evidence of Subsequent Corner Restoration

Year of search 1964 By Co. Hwy Dept.

Co Rd # 8

L.P. inplace - 350' W. of 4

1975 - Co Hwy Dept - Co Rd #4

USGLO Corner inplace

Bearing Trees, Reference Objects

Species Set Cedar post 3x3x6' High alongside iron

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

1959 - Co Hwy Dept Co Rd 8 GLO L.P. inplace
353' W. of 4

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____