Index No. E 23

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____

N1/4 1/2 Corner common to sections 1, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Tam	Tam
Diameter	10"	9"
Bearing	S2W	N22W
Distance	20 LKs	14 LKs

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1927 By GLO

Location filed Sec. of State

Monument Found old post and remains of both BITS.
Set 1X36" Ill. w/brass cap
1/4 S1
S12
1927

Bearing Trees, Reference Objects

Species No trees suitable for tres - pits are
Diameter impracticable - Set Cedar post, 8 long
Bearing 5" square 3' in ground alongside iron
Distance

Evidence of Subsequent Corner Restoration

Year of search 1961 By Pete Meyer

Found GLO monument in good condition.

Bearing Trees, Reference Objects

Cedar	Cedar	Cedar	
7"	6"	7"	
N46½E	N23W	S16½W	
19.5'	10.0'	17.9'	

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER, 1961

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____