Index No. P 22-23

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections 24

ON E-W 1/4 LINE



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1933

Original monument 1X36" I.P. w/brass cap C 5/24 1/0 SMC 1933

Bearing Trees

Species	Tam	Tam		
Diameter	20"	10"		
Bearing	N 53½W	S 82½W		
Distance	49 LKS	96 LKS		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Monument Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Oak	Elm		
Diameter	12"	11"		
Bearing	N12E	N36E		
Distance	64.1'	40.15'		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____