CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

___CENTER QUARTER___ Corner of Section __34__ ,Township __144__ , Range __30__ , __5th__ P.M.

STATE OF MINNESOTA, County of ___CASS___

At the corner location shown on the sketch:

☒ On __1/26/81__ found a ___GLO brass cap monument as set in 1930.___
      DATE

    ☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ placed a _____
      DATE

SKETCH OF REFERENCE TIES

-N-

Nail in
7" Cedar
N 62 E 28.36'
Scribed

Nail in
8" Cedar
N 14 W 16.60'
Scribed

O

1930-BT
10" Cedar
S 37 E 13.86'

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

signature   9-11-82
SIGNATURE   DATE

Registration No. _12684_

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

264968

OFFICE OF THE COUNTY RECORDER
County of ___Cass___

I hereby certify that this document was filed in the Co. Recorders office at _10:28 A._M. on the _14_ day of ___Sept.___ A.D., 19_82_

County Recorder _Beulah Hedrich_

By _M S_ _____,Deputy

DOCUMENT NO. _264968_

Mn/DOT 2105 (4-77)

Statement of Evidence:

1930   U.S. General Land Office dependent resurvey established this corner.
        and an iron pipe with a marked brass cap was set to mark the corner.
        The following bearing trees were marked: 5" Cedar S 37 E 21 links
        and 6" Cedar N 74¼ W 33 links.

1981   U.S. Forest Service technician G. Brama found GLO brass cap monument
        laying down. Straightened monument. The following bearing trees were
        found: 10" Cedar S 37 E 13.86' with scribe visible and 8" Cedar.
        (dead and leaning) N 74 W 21.78' with scribe visible. Two new bearing
        trees were marked and are shown on this certificate. Steel sign posts
        were set 3.1' east and 3.0' south of the corner.

1982   County Surveyor's Records in the Recorder's Office were checked and
        no resurvey information was found on this corner.

1982   Analysis of the above data indicates that the location of this Govern-
        ment corner has been perpetuated. I accepted the monument as marking
        the corner location as when set in 1930 by the GLO resurvey based on
        bearing tree evidence.