Index No. R5

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X (E) 460,274.26 Y (N) 220,028.71

NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument lost

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	J. Pine	J. Pine	J. Pine	J. Pine
Diameter	8"	9"	10"	7"
Bearing	S47W	S49E	N31½E	N82½W
Distance	32 LKS	9 LKS	13 LKS	10 LKS.

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 4/98 By DNR

Location filed CCSO

Monument Found Bridge spike, down 0.1' on ℄ ℄. Set 3/4" Iron rod with DNR Survey Cap.

Bearing Trees, Reference Objects

Species	NE Side Cor Bridge	P. Pole	Brace Post	
Diameter				
Bearing	N88°W	N40°E	S56°E	
Distance	112.99'*	44.18'*	47.36'*	

*distance to DNR RP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

R-5

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed

Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

May 1907; Twp Rd order shows no survey

July 1902; Twp Rd order shows no survey

Remonumentation certificate prepared 5/31/01 By J. Walker

Filed at Cass Co. Recorder #441850 Date _____