Index No. E11

CASS COUNTY LAND CORNER RECORD

T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____

N1/4 9 Corner common to sections 4, 9



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1866

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter NO TREE NEAR - TOO WET FOR MOUND

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed OCT 2003 By CCSO

Location filed _____

Monument Found c/m, down 0.2'; 1'± N of ℄ 76th st, 26'± W. of fence line to South.

Evidence of Subsequent Corner Restoration

Year of search 1985 By Freeman

Dug w/ backhoe - found nothing

1986 - Set cast iron in ℄ E-W Rd at proportioned position E-W.

1987 - Curo - Certificate - Doc # 297167

Bearing Trees, Reference Objects

Species	Elm stump	Elm	Elm	Elm stump
Diameter	7"	9"	7"	
Bearing	N 45° W	S61°E	S8°W	N72°W
Distance	48.21'	60.42'	24.25'	116'
	db/hd nail E side	db/hd nail S,	db/hd nail E.	

Bearing Trees, Reference Objects

Elm	Poplar		
14"	5"		
N72°W	N6°W		
116.00'	45.05'		

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Walt Curo - 1987 Doc # 297167

Sept. 1903, Twp rd order shows no survey

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____