Index No. L 9

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____

E 1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	N. Pine	B. Ane		
Diameter	8"	8"		
Bearing	N18E	S54W		
Distance	5 LKS	24 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1978 By Londecker & Assoc

Location filed _____

Monument Boundry of Miller Shore & Pineview North, corner lost.

Evidence of Subsequent Corner Restoration

Year of search 3/02 By WSN

Set 1/2" capped iron pipe at lost position.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

L-9

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument 5/2002 D. Rasmussen Cert. of Surv. shows mon found

12/03 WSN - Set PK over iron pipe, 12' W. of & and witnessed.

12" Pine NE, 56.39' to No. 1
Fence Post SW, 60.48' to PK in top
Fence Post NW, 55.49' to PK in top
A C of L was filed.

August 1905 WH Luffman
Twp Road order shows survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared #479088 By #16102

Filed at CCRO Date 1/16/04