Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 139 R. 26 M. 5TH Coordinates: X _____ Y _____

NE 22 Corner common to sections 14, 15, 22, 23



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees				
Species	TAM.	TAM	TAM.	W. PINE
Diameter	6"	6"	6"	8"
Bearing	N77E	N8W	S68E	S50W
Distance	23 LKS	11 LKS	21 LKS	28 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1909 By John Curo

Location filed County Survey Record Book "A" P390-398

Monument Fwd. Orig. Stake: Orig Bts: 8" w. Pine S50W 18.5'; 6" TAM N77E 15.2'

Set 3x3x36" TAM Post

Book "B" Pg. 91 Geo. Ralph. Ties - See Book "B" P.90-91

Evidence of Subsequent Corner Restoration

Year of search 1937 By CCC

Washburn Lake - BK # 3 P. 63

Sec. Cor in road.

1938 - BK#20 P.51 corner is S66½E 52' from control post at intersection of camp road & Hwy 6

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

N 17

Subsequent Corner Restoration

Year surveyed 1/25/88 By John Walker / DNR

Location filed Cert. Filed Doc. # 312283

Monument Found railroad spike at intersection of roads, flush with surface. Ties: 7"x5' wood post 308° 47.79'; transformer pole 75° 77.81'; 7" post brace for tele. junction box 121° 55.70'; 10" Tamarack 226° 64.06'.

Mar 1998 C.Co Land Dept. J.L., A.R.
Found mon. in roadway

July 1930 J.H. Flynn
Tiny and order shows survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____