Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 140 R. 31 M. 5TH Coordinates: X _____ Y _____
N1/4 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument lost

Bearing Trees

Species	B. PINE	TAM.		
Diameter	10"	6"		
Bearing	S89 1/4 E	SOUTH		
Distance	430 LKS	60 LKS		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1969 By DNR
Location filed Map & notes in file
Monument Fnd bent 1 1/2" pipe 1.3' below surface 1' S. of E-W Road Fence S.

Bearing Trees, Reference Objects

Species	Forestry Post	CFP	P.P	Birch
Diameter	Face			6"
Bearing	SSW	South	NNE	WSW
Distance	21.00'	52.31'	66.55'	91.70'
		N BC	N BC	N BC

Evidence of Subsequent Corner Restoration

Year of search 1914 By John Curo
microfilm - roll 115 BK 93 P. 136
start N. from L.P.

Bearing Trees, Reference Objects

N-15

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed
Monument

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - WALT CURO - 1975
Doc. #223893
found 2"x 20" bent pipe, remains of 2"x 48" pipe. Set cast iron monument 4" dia. top x 20" long 4" under surface of Twp. Rd. Ties: 8" Tamarack N 36°55' W 122.44'; 8" Tamarack N 04°27' W 104.28'; 6" White Oak S 04°33' E 58.20'.

May 2003 T. Freeman #21367
Cert. of Surv. shows Mon. found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____