Index No. V 9-10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

MC #21 Corner common to sections 28,33



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Lost

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	OAK	OAK		
Diameter	4"	7"		
Bearing	S74W	N87W		
Distance	34 LKS	24 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker

Location filed _____

Monument Set 2"x 48" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Maple	Burr Oak	Ash	
Diameter	7"	8"	8"	
Bearing	N 36 W	N 7 W	S 26 W	
Distance	39.81'	26.49'	58.99'	

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Certificate - David Landecker
Doc. # 312151

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____