Index No. 07-8

# CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____

SMC ON N'LY6 LINE Corner common to sections 20



O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1919

Original monument 1X36" I.P. W/BRASS CAP N 520/520 N SMC 1919

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | MAPLE | W. OAK | | |
| Diameter | 10" | 36" | | |
| Bearing | N74°44W | WEST | | |
| Distance | 78 LKS | 112 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1979 By Gary Stevenson

Location filed _____

Monument Found GLO brass cap monument in good condition.

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | Maple | Ash | W. Oak | W. Oak |
| Diameter | 23" | 10" | 7" | 12" |
| Bearing | N74W | NS7W | N21W | N4E |
| Distance | 51.5' | 107.38' | 96.44' | 102.43' |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - Gary Stevenson - 1982

Doc. #264925

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____