Index No. V23-24

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____

MC#2 Corner common to sections 25,36



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument 3" Yg. Pine

Bearing Trees

Species	Yg. Pine	Yg. Pine
Diameter	30"	24"
Bearing	S47E	N45W
Distance	68 lks	65 lks

Original Evidence Found

Year of search 1974 By BLM

Monument found Br. Cap

1917
Original Bearing Trees Found

Species	~~Stump hole~~	Bl. Oak
Diameter	1	11
Bearing	N45E	S51E
Distance	30 lks	109 lks

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed _____

Monument Br. Cap - 1"x36" for W.C.
no evidence found of original.
1916, E.B. Horst, Book "C" P.524 Fnd N.W. B.T. Stump
SETW.C. 59.5' EAST OF M.C. (IN LAKE)
also on microfilm - roll 115 BK 80 P 56

Bearing Trees, Reference Objects

Species	Ash	Oak	R. Oak 4"	R. Oak 4"
Diameter	6	8		
Bearing	N45E	S51E	N30-20E	S39-30W
Distance	30 lks	109 lks	20.6'	18.25'
	1918 TIES		1916 TIES	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - BREEZY POINT
J.F. PAMASEL 1919 W.S.W.C.MC.

PLAT - GISWOLD SUNNY BEACH ADDITION
W.J. SPAIN 1974 W.C

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____