Index No. R9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____

NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Bearing Trees

Species	Tam	Fir	N. Pine	Tam
Diameter	6"	10"	5"	7"
Bearing	S46W	S43E	N42E	N42W
Distance	31 LKS	49 LKS	25 LKS	15 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSM RLS #16089

Set a 2"x24" galv. steel pipe w/ brass cap, on ⌖ below surface.

Steel Sign Post, South, 32.39

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Oak	Aspen	Aspen	Tamarack
14"	9"	6"	9"
N20°W	S22°E	N19°E	S6°W
45.02'	83.99'	42.29'	85.65'

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared NLSM By NLSM

Filed at CCRO Doc. #412852 Date 5/17/99