Index No. R21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____

NE 26 Corner common to sections 23,24,25,26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Fir	Cedar	Fir	Birch
Diameter	10"	14"	10"	10"
Bearing	54½E	54½W	N68W	N20E
Distance	28 LKS	38 LKS	33 LKS	5 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1928 By GLO

Location filed Sec. of State

Monument Found 2½" galv. I.P. up 12 inches with unmarked iron cap. County Surveyors restoration Corner. no trace of orig B.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1964 By Co. Hwy Dept

Co. RD #8

Found I.P. inplace - E. of road

1975 - Co Hwy Dept - Co RD #4

2" I.P. inplace

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

1959 - Co Hwy Dept - I.P. E. of Hwy

Subsequent Corner Restoration

Year surveyed 1916 By H.F. Baldwin

Location filed microfilm - roll 115 BK 77 P. 53

Monument Set I.M. proportionally

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - Gary Stevenson - 1982

Doc. # 204935

Found 2" capped galvanized iron pipe as set in 1916.

9" Ash N73W 58.7';

27" W. Pine S10W 60.35';

27" Spruce N79E 84.35';

28" W. Pine N28E 164.50"

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____