Index No. L 19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____

C1/4 Corner common to sections 14



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1926

Original monument 1x36" I/P w/brass cap C1/4 5/14 1926

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	Tam	Tam
Diameter	8"	10"
Bearing	S53E	N51-15W
Distance	43 Lks	36 Lks

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1963 By Pete Meyer

Location filed _____

Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Tamarack	Tamarack
Diameter	7"	7"
Bearing	S 38E	S 51 W
Distance	41.3'	18.9'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1963

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____