Index No. V5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____

NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument lost

Bearing Trees

Species	Basswood	Ironwood	Ironwood	Balsam
Diameter	16"	4"	6"	5"
Bearing	N23W	N69E	S11E	S47W
Distance	38 LKS	22 LKS	28 LKS	16 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1907 By John Curo

Location filed County Surveyor Record Book "A" P246-247

Monument Set wood stake from QR16 B.Ts: 16" Basswood N23W 25.1', 4" Ironwood N69E 14.5', 6" Ironwood S11E 18.5', 5" Balsam S47W 10.6'

Bearing Trees, Reference Objects

Species	Maple	Maple	Maple	Balsam
Diameter	8"	14"	8"	10"
Bearing	N76-15E	S50E	S0-30W	N67-30W
Distance	63 LKS	96 LKS	72 LKS	134 LKS

Evidence of Subsequent Corner Restoration

Year of search 1926 By GLO

Fnd wood stake and NW, SE, SW B.T. Stumps

Set 2x36" I.P. w/brass cap

T14N R29W

530	529
531	532

1926

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE — BILL OKERMAN — 1969

found GLO monument in good condition.

5" Elm N12W 22.58';

4" Elm N23E 25.35';

5" Elm S46E 25.45';

7" Elm S53W 58.80'.

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____