Index No. G 9

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X (E) 399627.54 Y (N) 281651.27

E 1/4 8 Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Post

Bearing Trees

Species	Balsam	Cedar
Diameter	6"	8"
Bearing	N31E	N23W
Distance	11 LKS	24 LKS

Original Evidence Found

Year of search ____ By ____

Monument found ____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1910 By JAMES MIDDLETON

Location filed COUNTY Book "B" P.578

Monument FND CEDAR Post SET From GLO GRANT BITS: 6" BALSAM N31E 11 LKS, 8" CEDAR N23W 24 LKS SET 4" CEDAR HUB FND CO. RD. SURVEY BITS: 9" CEDAR N57-16E 67.47', 15" CEDAR N49-42W 60.25'

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search 1930 By GLO

Fnd stumps of both B.T.S set 1X36" I.P. w/brass Cap

1/4
S8/S9
1930

Bearing Trees, Reference Objects

Cedar Snag 16"	Cedar Snag 7"			
S63 1/4E	N36W			
85 LKS	33 LKS			

G-9

Subsequent Corner Restoration

Year surveyed 1925 By Minn. Hwy Dept.

Location filed R/W map in Recorder's office - Walker to Cass Lake

Monument 1" iron pipe w/ brass plug

4/2002 File #2002.009 CCSO found GLO Brass cap, 407'± E. of ℄ Hwy. #371, up 0.8' at edge of low ground. GPS location, add new witnesses:

4" Balsam	N42°W,	32.46' *
6" Ash	S78°E,	27.04' *
8" Ash	S64°W,	11.50' *

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search ____ By ____

Remonumentation certificate prepared ____ By ____

Filed at ____ Date ____