

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 28, Township 142, Range 27, 5th P.M.

STATE OF MINNESOTA, County of Cass


At the corner location shown on the sketch:

On 1/14/81 found a USGLO brass capped iron pipe in good condition.
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

260595

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Samy H. Stevenson 12-2-81
SIGNATURE DATE

Registration No. 12684

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:55 A.M. on the 3 day of Dec. A.D., 1981

County Recorder Berulah Hardin

By MS, Deputy

DOCUMENT NO. 260595

MICROFILM

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 6" Fir S 32° W 10 links, 14" Poplar S 78° E 15 links, 10" Fir N 71 E 14 links, and 8" Fir N 15 W 25 links.
- 1919 U.S. General Land Office dependent resurvey found the corner marked by a wooden post at the corner and the stumps of three of the 1873 bearing trees as follows: 12" Cedar stump S 32° W 10 links, Poplar stump S 78° E 15 links, and 12" Cedar N 15° W 25 links. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 14" Spruce N 25½° E 89 links, 12" Ash S 36½ E 84 links, 12" Ash S 63½ W 17 links, and 6" Ash N 28° W 52 links.
- 1941 U.S. Forest Service records show the following: A corner card dated 2/12/41 by R.T. DeFant under the CCC program shows the brass cap iron pipe found.
- 1971 R.F. Schneider, RLS, found the brass cap monument and took the following ties: 6" Elm N 65° E 33.30', 12" Elm S 40° E 56.77', and 6" Ash N 60° W 14.00'.
- 1981 Found the brass cap monument in place in good condition and took new ties as noted on this certificate. The only evidence of the GLO bearing trees found was a stump depression that fit the call given to the 14" Spruce in 1919.