



Statement of Evidence:

- 1918 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 9" W. Oak N 45° W 25 links and 9" W. Oak S 5½° W 31 links.
- 1980 USFS technician Gary Brama found the GLO brass cap in place and the SW bearing tree and the stump of the NW-bearing tree. New bearing trees were marked and are shown on this certificate. Steel sign posts were set north, west, and south.
- 1981 On Dec. 8, I visited corner and found items as per 1980 USFS report. The stump of the NW 1918 bearing tree had visible scribing. The SW 1918 bearing tree had been cut open and scribing found.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.

