| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER WEST 1/16th Corner of Section 16&21 ,Township 141 ,Range 29 , 5th P.M. STATE OF MINNESOTA, County of CASS | |
|---|--|
| At the corner location shown on the sketch: | |
| On 7/3/80 found o marked GLO brass cap monument in place as set in 1918. On THE FOUND TO THE PROPERTY OF THE PRO | |
| ☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain) | |
| Onplaced a | |
| SKETCH OF REFERENCE TIES | |
| SKE TOTI OF INCIDENCE TIES | |
| 4 | |
| - N | |
| | Mail in |
| Nail in | 9" R. Oak |
| 10" R. Oak | N 2 E 37.14' Scribed |
| N 74 W 50.94 | · Scribed |
| Scribed ; | |
| 3.1 | ÷ |
| ₹ ; 3 · | |
| | |
| | |
| | 43 |
| 1918-GLO-BT | 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1 |
| 26" R. Oak West 129 links | Nail.in - |
| West 129 IIIks | 8" R. Oak |
| | S 84 E 73.17' Scribed |
| | SCLIDER |
| | |
| | |
| | |
| | |
| | BEARINGS ARE APPROXIMATE |
| Statement of evidence relative to this corner loc | cation is on back of page. |
| Statement of evidence relative to this corner location is on back of page. | |
| I hereby certify that this document and the data | OFFICE OF THE COUNTY RECORDER |
| contained herein was prepared by me or under | County of Con |
| my direct supervision. | I hereby certify that this document was filed in |
| | the Co. Recorders office at 9:43 A. M. on the |
| Many H. Stavenon 12-29-81 SIGNATURE DATE | 31 day of Dec. A.D., 1981 |
| Registration No. 12684 | County Recorder Beulah Herdinks |
| 1 | By M S ,Deputy |
| ▼ Land Surveyor, □ Professional Engineer | |
| ☐ County Surveyor, ☐ County Engineer | DOCUMENT NO. 361005 |

Statement of Evidence:

- U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 12" Oak West 129 links and 8" Maple N 21 W 250 links.
- 1980 USFS technician Gary Brama found the GLO brass cap monument in place up 4" in good condition. The Oak bearing tree was found alive. No evidence was found of the Maple. Three new bearing trees were marked and are shown on this certificate. A steel sign post was set 2.5' east of the corner.

.. - -

- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- On Dec. 22, I visited the corner and found items as per the 1980 USFS report. The 1918 Oak BT had visible scar. I accepted the found monument as marking the same position as when originally set in 1918.