

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 27, Township 141, Range 29, 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 9/24/80 found a marked GLO brass cap monument in good condition.  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

261358

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

*Samy H. Stevenson* 2-1-82  
SIGNATURE DATE

Registration No. 12684

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

### OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:30 A.M. on the 2 day of Feb. A.D., 1982

County Recorder *Beverly Hendrichs*

By MS, Deputy

DOCUMENT NO. 261358

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" Birch N 20 W 16 links and 6" Maple S 31 E 19 links.
- 1918 U.S. General Land Office dependent resurvey reestablished this corner by proportional measurement between section corners. No evidence was found of the original post or bearing trees. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 8" Bl. Oak S 32-45 E 175 links and 14" Bl. Oak N 63-15 W 63 links.
- 1965 Corner certificate by William Oberman, RLS #6807, shows GLO brass cap monument found in place in good condition. Only evidence of the bearing trees found was a stump hole at the bearing and distance called for to the NW Bl. Oak. Two new bearing trees were taken and marked: 5" Maple N 48 E 17.5' and 9" Oak S 86 E 12.9'. Certificate was filed 6/28/68.
- 1980 USFS technician W. Olson found the GLO brass cap monument in place in good condition. The 1965 Oak bearing tree was found with scar grown over. The stump of the 1965 Maple was found with scribing. Two new bearing trees were marked and are shown on this certificate. A steel sign post was set 4.0' north of the corner and one was found 5.50' east of the corner.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 Corner was visited on Jan. 29 and items found as per 1980 USFS report. This certificate is made to update the 1965 certificate.