

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 21, Township 141, Range 31, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 3/28/80 found a County cast iron monument as per certificate filed  
DATE  
in 1975 by R.F. Schneider
- left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

## SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

261364

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Mary H. Stevenson  
SIGNATURE

2-1-82  
DATE

Registration No. 12684

- Land Surveyor,  Professional Engineer
- County Surveyor,  County Engineer

### OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:05 A.M. on the 2 day of Feb. A.D., 1982

County Recorder Beneah Hendricks

By M S, Deputy

DOCUMENT NO. 261364

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" W. Pine S 34 W 39 links and 14" N. Pine N 54 E 20 links.
- 1962 USFS technician C. Krause searched four man hours for this corner, but found no evidence of this corner.
- 1975 R.F. Schneider, RLS #5740, found no evidence of this corner. A county cast iron monument was set at the lost position, midway and on line between the NE and SE corners of Sec. 21. Three tie trees were taken and a corner certificate filed.
- 1980 USFS technician Gary Brama found the cast iron monument in place and tie trees as per 1975 certificate. Three new bearing trees were marked and steel sign posts were set 2.3' north and 2.9' south of the corner.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Jan. 11, I visited the corner and found items as per 1980 USFS report. Based on the 1975 certificate by R.F. Schneider, the monument marks the lost position of the corner. The tie trees shown on this certificate show both the USFS new ties and R.F. Schneider's ties.