

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTHEAST Corner of Section 21, Township 141, Range 31, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 4/8/80 found a marked brass cap monument as per certificate filed
DATE
in 1963 by Peter Meyer
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

261365

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Mary H. Stearns

SIGNATURE

2-1-82

DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:10 A.M. on the 2 day of Feb. A.D., 1982

County Recorder Beverly Hendrichs

By MS, Deputy

DOCUMENT NO. 261365

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 8" Y. Pine N 72 E 52 links, 14" Y. Pine N 14 W 84 links, and 10" Y. Pine S 53 E 22 links.
- 1962 USFS technician R. McDonald found 3 burned pine stumps at the correct bearing and distances for the GLO notes and remains of burned wood at the corner location. A 2" x 60" galvanized iron pipe with a 3" marked brass cap was set for the corner and two new bearing trees marked: 6" Oak N 37. W 46.0' and 8" Aspen N 66 E 15.0'. The brass cap was marked with RLS #3628.
- 1963 Corner certificate filed by Peter Meyer, RLS #3628 showing the same information as listed in 1962 USFS report.
- 1975 R.F. Schneider, RLS #5740, found the brass cap monument as set by the USFS and accepted same as the corner.
- 1980 USFS technician G. Brama found the brass cap monument as set in 1962 up 1.5'. Both 1962 tie trees were found, but the Aspen had been partially cut by beavers. One new tie tree was marked and two sign posts set as reference points as shown on this certificate. Also steel sign posts were set 2.19' east and 4.0' south of the corner.
- 1982 January 11 visited corner and found items as per 1980 USFS report. This certificate was made to update the 1963 certificate.