CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER		
CE 1/16 Corner of Section 1	,Township <u>141</u> ,Range <u>30</u> , <u>5</u> P.M.		
At the corner location shown on the sketch:  On 10-8-81 found a 1"x 36" iron pipe with brass cap standing  on placed a p			
		Onplaced a	
		SKETCH OF F	REFERENCE TIES
		4	•
	10"RED OAK		
SIGN, Eig	N5531.16		
WEST			
3.4'			
	E. Z. E.		
637/11	6" RED OAK		
9" RED OAK			
not to scale			
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data	362608 OFFICE OF THE REGISTER OF DEEDS		
contained herein was prepared by me or under	County of		
my direct supervision.	I hereby certify that this document was filed in the Reg. of Deeds office at 10:50 A.M. on the		
Mathelan 12-8-81 SIGNATURE DATE	7 day of May A.D., 19 82		
Registration No. 11395  B Land Surveyor,  Professional Engineer	Register of Deeds Dealah Hadruh  By MS  Deputy		
County Surveyor C County Engineer	DOCUMENT NO. 262608		

In 1917, Earl G. Harrington a US surveyor set a 1"x36" iron pipe with brass cap for CE 1/16 from which he made the following BT's. A 5" white oak  $S49\frac{1}{2}$  E 184 LKS and a 8" jackpine  $S44\frac{1}{4}$  W 133 LKS.

On October 8, 1981, Walter Curo and Paul Johnson find the brass cap monument standing in good condition. We search for the original Bt's, but find no trace of either one. We make new BT's as shown on front.